

DEPARTMENT OF						SURVEY	CG-2541	OAST GUARD I-D11 (Rev10/97)
INSTRUCTIONS: 1. Submit this report to the Auxiliary Coordinator as soon as possible after conducting the survey. 2. The best time to survey bridges is shortly before sunset so you can observe any hazards or discrepancies before dark, then observe the lights after dark. 3. If conducting the survey by land, respect all property rights. DO NOT TRESPASS. 4. Auxiliarists do not have law enforcement authority. Take care that your survey is not interpreted as a law enforcement action. 5. Minor discrepancies (e.g. one light out, clearance gauges hard to read) should be reported by mail. More serious problems (e.g. most or all lights out, hazards to navigation, bridge malfunction) should be reported to the nearest Coast Guard Group Office by telephone or radiotelephone. If in doubt, report it.								
NAME OF BRIDGE Channel Is Blvd (West)					ATIT 34	UDE 10.6' N	119 13.7	, M
NAME OF WATERWAY Channel Is Harbor					MILES ABOVE MOUTH TYPE OF BRIDGE F			
NAME/ADDRESS OF BRIDGE OWNER City of Oxnard P.O. Box 1192 Oxnard CA 93030 Fill out the section below and annotate the diagram on the reverse. Show north as								
Fill out the section	below and ann	otate the di	agram	n on the	reve	rse. Show north	errow or direction	of current.
TYPE OF LIGHTS	Number of Lights	of Correctly of Proper Visible for					State Condition of Lights	
Channel Center Lights	4							
Margin of Channel Lights	0							
Pier Lights	6 .							
Pier Axis Lights	0	<u>.</u>						
Movable Span Lights	0							
Preferred Channel Lights	0				•		<u> </u>	
OTHER FEATURES	How Many?	LLNR	Characte		eristic Range		Work	ing Properly?
Fog Signals	0	0		N/A		N/A		
Racons	0	0		N/A	·	N/A		
Condition of fenders: Is the bridge name shown? Are navigational clearances in Is there any equipment (e.g. b	arges, scaffold	epair, cable s) in the na	s, etcʻ vigatio	? Ar	re na s tha		is sign visib aired by accumu	le to mariners? lation of debris?
If a drawbridge, is it capable of operating? Are the operating regulations posted? Discrepant Use there evidence of bridge or fender damage that might be from vessels? Watching properations							screpant atching properly	
Date and Time of Survey	Name and	Name and Member Number						phone Number
Date and Time of Salvey	Signature of Surveyor				Aux . File l	Number 6		

Secondary Observer(s):	Aux. #:
	Aux. #:
	Aux. #:
	Aux. #:



NORTH ARROW



FIXED BRIDGE
(2 MARKED NAVIGATION OPENINGS)
(no axis lights)

Comments:

